Deister Farmstead State Road 422 Stull Vicinity Douglas County Kansas

HABS KANS 23-STUL.V,

REDUCED COPIES OF MEASURED DRAWINGS

ADDENDUM FOLLOWS...

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Addendum to
Deister Farmstead
Route 442
Stull Vicinity
Douglas County
Kansas

HABS No. KS-36

HABS KANS 23-STUL.V,

## **PHOTOGRAPHS**

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

## Historic American Buildings Survey UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS KANS, 23-STULV,

1-

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Kansas	Douglas		Stull Vicinity	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)  HABS NO.				
Deister Farmstead				KS-36
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
Route 442				
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)		
c. 1870		Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
The Deister Farmstead is representative of a way of life on a working farm in the early years of Kansas' history. Henry Deister bought the farm in the 1860s and is typical of the				
large number of German immigrants who settled this area in the late 19th century.				
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
EXTERIOR FEATURES DF NOTE				
House, Stone Barn, Smoke-chickenhouse and Wash-Utility shed all are constructed of rough-cut limestone quarried on the farm; All are excellent examples of early Kansas				
stone vernacular architecture.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
House 1903, new interior woodwork; also addition of cistern and hand pump in the kitchen 1928, new wiring, fixtures, furnace and ductwork				
1950s, south porch removed				
PRESENT CONDITION AND USE				
OTHER INFORMATION AS APPROPRIATE				
See drawings for additional information.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
COMPILER, AFFILIATION M. McDona	ald HABS Histo	rian	,	DATE 7-31-84